



Government of Tripura
Office of the Sub-Divisional officer
PWD (R&B), Dharmanagar Sub-Division
Dharmanagar, North Tripura.

No. F. 25-1 / PWD/ SD/DMR/ 409

Dated, Dharmanagar, the 24 /08/2026

To,
The Principal,
Golden Valley H.S School
Padmapur, Dharmanagar, North Tripura.

Subject :-Forwarding of Building Safety Certificate.

Reference : your letter No F.33/GVHS/2026/CBSE(AFFL)/2418 dated 20/06/2026.

Sir,

With reference to the subject and the letter cited above, the Building Safety Certificate is forwarded herewith, as requested in your above-mentioned letter. This is for your kind information and necessary action.

Thanking you.


SDO, PWD(R&B)
Dharmanagar Sub Division
Dharmanagar, Tripura (N)

Enclosures:-

1. Safety Certificate
2. Line Sketch of the Building Blocks

BUILDING SAFETY CERTIFICATE

No.

Dated: 24/08/2026

Certified that the existing building **Golden Valley H.S School** at Rajbari, Dharmanagar comprised of Nil basement(s) and 3 Nos (1 No single storied Semi Structure building CGI Sheet roofing & 2 Nos G+1 storied RCC frame building) blocks (owned/ occupied by Golden Valley H.S School have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of PWD (R&B), Govt of Tripura, on 24th Aug 2026 in the presence of Manas De, Principal, Golden Valley H.S School and out of the 3 blocks, 2 blocks of the building/premises are found to be fit for occupancy up to Class XII with effect from 24th August 2026, for a period of one year, subject to compliance with the specific conditions as appended.

- Any proposed addition, alteration, extension, renovation, or modification to the building shall be carried out only under the supervision of a qualified and competent Engineer. Upon completion of such work, a fresh Structural Safety Certificate shall be obtained from the undersigned before the building is put to use.
- In the event of any natural calamity, such as flooding, earthquakes, storms, or similar occurrences, or if any signs of structural distress are observed including settlement of foundations, cracks in walls, sagging of roofs, excessive deflection, or any other structural defects the School Authority shall immediately arrange for an inspection by the undersigned or another qualified structural engineer to assess the building's structural stability and safety. Appropriate remedial measures, if required, shall be undertaken before continued occupancy of the building.

Details of Building:-

Sl No.	Name of Block	Plinth Area	Type of Building	Year of Construction	Remarks
01	Block A	15 m x 12 m	RCC frame Structure, G+1, (1 st floor roofing is of GCI sheet)	2009	This is an old block requires, minor maintenance works, including plastering and painting, trimming of vegetation. In addition, waterproofing treatment is required at necessary locations to prevent seepage and further deterioration of the building.
02	Block- B	44 m x 11 m	RCC frame Structure, G+1, With Concrete roofing	2025	New Block
03	Block- C	36 m x 8 m	Semi-Permanent Structure with GCI Sheet Roofing	2002	Dilapidated condition

Issued on 24th Aug 2026 by SDO PWD (R&B), Sub -Division, Dharmanagar, North Tripura.

Manas De
25/08/26
(Manas De)
Principal
Golden Valley H. S. School
Rajbari, Dharmanagar, (N) Tripura.
Phone No. 9670027

Chandra
SDO, PWD (R & B)
Dharmanagar Sub-Division
Dharmanagar, North Tripura

Golden Valley Higher Secondary School, Rajbari, Dharmaganagar



ROAD

Block- A : Old Admin Block
G+1- (180 SQM)

Block B, New G+1 Academic Building (484 SQM)

SDM
Kitchen
24 SQM

Block C, Old Academic Building (288 SQM)

[Signature]

[Signature]
S. D. O. (P.W.D.)
Dharmaganagar Sub-Division
Dharmaganagar

#Line Sketch, Not to Scale